

# **HONG KONG BIRD-WINDOW** COLLISION



## **WHAT IS BIRD-WINDOW COLLISION?**

Two main factors causing birds to collide with glass:



# DOES IT OCCUR IN HK?

A total of 309 bird victims were recorded just over one year period in 2022/2023, which is worrying.

**DISTRIBUTION OF BIRD-WINDOW COLLISIONS** IN HONG KONG (9/2022-8/2023)



# **HOW TO REPORT?**

You can upload the following information to the Global Bird Collision Mapper:



On-site Photos







Photo of bird or imprint with the Bird collision card







**Date and Time of Encounter** 



Bird Status

Choose: ☐ Dead ☐ Alive ☐ Multiple birds For bird imprint, please fill in unknown

Species (Optional)Notes (Optional)


Further descriptions of the bird, imprint, weather conditions or building characteristics are encouraged.

Proceed to the Globa **Bird Collision Mapper** and its user manual





# **HOW TO DEAL WITH THE BIRD?**



Glass structures within

Transfer to KFBG in

person (2483 7200)


## **IDENTIFY BIRD COLLISION IMPRINT**

If you find at least two of the following clues on the glass surface, please take pictures of the imprint and report to the Global Bird Collision Mapper.



# SOLUTION

For existing buildings, the bird collision risk can be reduced by 90% if visual markers (e.g. stickers, curtains or hanging ropes) that meet the requirements below are



#### Requirements

- Opague and Non-reflective
- With min. diameter/width of 6mm

**Bird Excrement** 

- Not more than 5cm apart
- Installed on the outer surface

